

GOVERNMENT OF TELANGANA
ROADS AND BUILDINGS DEPARTMENT

From
Sri Y.Suresh, M.Tech.,
Executive Engineer(R&B)
Division Nizamabad.

To
The Secretary & Correspondent,
SSR School, Jannepally, Navipet
District, Nizamabad.

Lr. No.DB/T4/ Soundness Certificate/2023-24/819 Dt: 13-09-2023

Sir,

Sub:- (R&B) Dept.- Issue of Structural Soundness Certificate to
SSR School, Jannepally, Navipet, Nizamabad in Nizamabad district-
Report- Reg

Ref:- 1) Your Application Lr. No. Nil, Dt:06-09-2023.
2) Dy.E.E (R&B) SD-BDN/SSR School/ Jannepally/Soundness/2023-24/
Dt:12-09-2023.

@@N@@

The Dy. Executive Engineer (R&B) Sub-Division, Bodhan vide reference 2nd cited, reported that the, SSR School, Jannepally, Navipet in Nizamabad district and the building consisting of (G+1) floors only with Rcc framed structure and it is observed in celing of some class rooms due to dampness paint is peeled off. It may be recitified.

The Geo Co-ordinates of the Building are:-

Latitude 18°- 48' 27.40" N.
Longitude 78°- 03' 41.94." E.

Based on the report of Dy.Executive Engineer, it is informed that the above school building is structurally sound and fit for occupation for the acadamic year 2023-24.

Yours faithfully,

uu - 5/13/24
Executive Engineer (R&B)
Division, Nizamabad.

13/9/24

[Signature]
PRINCIPAL
SSR SCHOOL
Vill: Jannepally, Mdl. Navipet,
Dist. Nizamabad. (T.S.)-503246
Affiliation No. 3630127.

[Signature]
Secretary & Correspondent
SSR SCHOOL
Vill: Jannepally, Mdl. Navipet,
Dist. Nizamabad. (T.S.)-503246
Affiliation No. 3630127.